

Computer Aided Manufacturing



**Dr.S.RAMABALAN,
PRINCIPAL,
E.G.S. PILLAY ENGINEERING COLLEGE,
NAGAPATTINAM.**



Cleansing through Breathing

Nadi Suddhi
(Alternate
Nostril breathing)



1 min

Recap and review of previous class

Let's
Recap



5 mins

Unit III

PROGRAMMING OF CNC LATHE

Coordinate system - structure of a part program -G & M Codes - Programming for FANUC and SIEMENS controller -Single pass and canned cycle -Turning, facing and threading -Multi-pass canned cycle -Rough and Finish turning, facing, pattern repeating, grooving, threading, drilling, boring, peck drilling, high speed drilling cycle - **Subprogram and Macro programming -Tool length and nose radius compensation - offset -Tool, work and coordinate -Insert - Materials, Classification, Nomenclature and Selection** -Tool and Work holding devices -Automatic tool changer -Turret and drum type -Tool holder nomenclature and selection -CNC part programming using CAD/CAM software and interfacing with CNC machines

Prerequisite Knowledge

- CNC Programming

3.EVOCATION



4. GENERAL OBJECTIVE (GO)

➤ Students will be able to apply the appropriate programming method for fabrication of components with necessary settings.


5. SPECIFIC OBJECTIVE (SO) MAPPED WITH STEM

The students will be able to

1. Exemplify the needs of the subprogram and macro program concept in CNC part programming. (U-C) (E)
2. Exemplify the tool nose radius compensation for different lathe operations. (U-C) (E)
3. Compare tool offset and work offset in CNC lathe. (U-C) (E)
4. Explain the four types of insert materials, nomenclature and selection of insert for given work material. (U-C) (E)

CONCEPT OF SUBPROGRAM


- CNC lathe program which **calls a subprogram multiple times** to cut the same pattern.
- Subprogram uses **UW instead of XZ** to make program easier to understand and debug.



SUBPROGRAM


- Main Program:
- O0005
- N5 G90 F0.2 S1200 T0101 M04
- N10 G00 X40 Z0
- **N20 M98 P37000 (call subprogram O7000 three times)**
- N30 G01 W-30
- N40 G28 U0 W0
- N50 M05 M30

- Subprogram:
- O7000;
- G01 U0 W-30
- G02 U0 W-10 R5
- N60 M99



MACRO PROGRAMMING

- Macros can be used to
 - ✓ automate repetitive tasks
 - ✓ document what you did
 - ✓ share common procedures
 - ✓ add tools to the toolbar
 - ✓ add keyboard shortcuts



- Part Program prepared using variables
- Arithmetic operations possible
- Conditional statements like GOTO , DO WHILE are used
- For developing user defined cycles
- Can be easily called from user program


Range of Custom Macro Variables

Variable number	Type of variable	Function
#0	Always null	This variable is always null. No value can be assigned to this variable.
#1 – #33	Local variables	Local variables can only be used within a macro to hold data such as the results of operations. When the power is turned off, local variables are initialized to null. When a macro is called, arguments are assigned to local variables.
#100 – #199 #500 – #999	Common variables	Common variables can be shared among different macro programs. When the power is turned off, variables #100 to #199 are initialized to null. Variables #500 to #999 hold data even when the power is turned off.
#1000 –	System variables	System variables are used to read and write a variety of NC data items such as the current position and tool compensation values.

Example – 1


- **O0002;**
- N10 G21 G94;
- N20 G91 G28 Z0;
- N30 T01 N06 D01;
- N40 G90 G54 X0 Y0 Z100;
- N50 G65 P5000 X100 Y50 R30 Z-50 F500 I100
A0 V45 H5; N60 M30;

-
- **O5000;**
- N10 #3=#4003;
- N20 G81 2#26 R#18 F#9 K0;
- N30 N1 WHILE[#11GTO]D01;
- N40 #5=#24+#4*COS[#1];
- N50 #6=#25+#4*SIN[#1];
- N60 G90 X#5 Y#6;
- N70 #1=#1+#2;
- N80 #11=#11-1;
- N90 END1;
- N100 G#3 G80;
- N110 M99;



Tool length and nose radius compensation





WORK COORDINATE SYSTEM OR WORK ZERO OR WORK OFFSETS (G54-G59)


- **Machine Zero** – Machine Builder
- **Work Zero** – Point Assumed in the **work-piece** for giving its dimensional value called as work zero.
- **Offset** – the **distance of W/s zero from M/c zero** is called offset.
- Basic work offsets are very simple to specify: simply enter one of **G54, G55, G56, G57, G58, or G59**. Most machine startup with G54 selected. It's a good practice to put a G54 into the safety line at the top of all of
- your g-code programs to make sure you know what work offset is being used unless you have reason to want to leave that aside.


Reference Points

M = Machine zero point.
(unchangeable ref. Point determined
by machine manufacturer)

N = Tool mounting reference point

W = Work piece zero point. (can be
freely determined by the
programmer and can be moved
within program)





09:14:31
2012/06/25

M [100]

N: \MPF\SIEMERIK_808D.MPF

SIEMENS

Reset

MCS	Position	Repos offset	T,F,S
X	61.750	0.000 mm	T 1 D 1
Z	188.900	0.000 mm	F 0.000 100% 0.000 mm/min
			S1 0.0 100% 0.0 II

G01 GS00(0) G60

Tool measurement manual

Ø 59.300 mm

Length X(L) 64.200 mm

Compensation data have been activated!

T,S,M Set REL Meas. tool Manual Sett.

WORK SHIFT

00002 N00200

	(SHIFT VALUE)		(MEASUREMENT)
X	0.000	X	0.000
Z	-98.100	Z	0.000

A) ^

S OL 0%


MEM *****

11:44:58


W. SHFT

(OPRT) +

Work piece (1)



Work piece (2)



TOOL NOSE RADIUS COMPENSATION

- **Function and purpose**
- The tool nose is generally rounded and so a hypothetical tool nose point is treated as the tool nose for programming .with such a programming, **an error caused by the tool rounding arises during taper cutting or arc interpolation** between the actually programmed shape and the cutting shape. Nose R or Tool radius compensation is a function for automatically calculating and offsetting this error by setting the nose radius or tool radius value.

TOOL NOSE RADIUS COMPENSATION

- **Programming Format:-**
- G40 = Nose R/Tool radius compensation mode cancel
- G41 = Nose R/Tool radius compensation left mode ON
- G42 = Nose R/Tool radius compensation right mode On

1. G40 serves to cancel the tool nose radius compensation mode.
2. Tool nose radius compensation function pre reads the data in the following two move command blocks and controls the tool nose radius center path by the intersection point calculation method so that it is offset from the programmed path by an amount equivalent to the nose radius .
3. The tool nose radius compensation amount corresponds to the tool length number and it should be preset with the tool nose point.
4. Tool nose radius compensation function is also valid for fixed cycles (G77 to G79 or *G90 to G92) and for roughing cycles (G70, G71, G72 and G73). However, in the roughing cycles, the tool nose radius compensation function
5. If four or more blocks without move commands exist in five continuous blocks, overcutting or undercutting will result. However, blocks in which optional block skip is valid are ignored. Applied for finish shape is cancelled and upon completion of the roughing, NC unit will re-center the compensation mode.
6. With threading commands, compensation is temporarily cancelled in one block before.

INSERT

- Another name for a **tipped tool**, a cutting tool used in metalworking.
- General turning inserts come in variety of shapes and sizes. One thing is important to remember and understand is that **every turning insert has a nomenclature associated with it.**

Turning Inserts

- Turning inserts are specified by their **ANSI insert designation** that provides a shorthand method for identifying the shape and size of an insert.

MATERIALS

- Carbide
- Ceramic
- Cermet
- Diamond

CLASSIFICATION

- Turning Inserts
- Grooving Inserts
- Threading Inserts
- Drilling Tools
- Boring Tools



SCMT-HM



SD



SEET-DR



SEET-DM



SEHT



SEKN



SNKN



SNMA



SNMG-DF



SNMG-DF



SNMG-DM



SNMG-DM



SNMG-EF



SNMG-PM



SPG



SPKN



SPU



TCMT-HF



TCMT-HM



TCMT-HR



TNMA



TNMG



TNMG-DF



TNMG-DF



TNMG-DM



TNMG-DM



TNMG-EF




TNMG-PM



TNMM



TNMM



TPGH



TPG



TPGN



TPKN



TT/TPMM



TRMR



TPU



TPUN



VBMT-HM



VBMT-HR



VNMG-DF



VNMG-DF



VNMG-DM



VNMG-DM



VNMG-EF



VNMG-PM



WCMX



WNMA



WNMG-DF



WNMG-DM



WNMG-EF



WNMG-PM

Nomenclature- Insert

A – Parallelogram 85°
B – Parallelogram 82°
C – Diamond (Rhombic) 80°
D – Diamond (Rhombic) 55°
E – Diamond (Rhombic) 75°
H – Hexagon
K – Parallelogram 55°
L – Rectangle
M – Diamond (Rhombic) 86°
O – Octagon
P – Pentagon
R – Round
S – Square
T – Triangle
V – Diamond (Rhombic) 35°
W – Trigon 80°

SHAPE

N – 0°
A – 3°
B – 5°
C – 7°
P – 11°
D – 15°
E – 20°
F – 25°
G – 30°
NP – 0° 10°

RELIEF ANGLE

Insert Incribed Circle (I.C.) Thickness

A = ±.0002	±.001
B = ±.0002	±.005
C = ±.0005	±.001
D = ±.0005	±.005
E = ±.001	±.001
^{1,2} F = ±.002 to ±.004	±.002
G = ±.001	±.005
¹ M = ±.002 to ±.010	±.005
¹ U = ±.005 to ±.012	±.005

TOLERANCE CLASS

Number of 1/8ths on inserts 1/4" Incribed Circle (I.C.) and over.

Number of 1/32nds on inserts less than 1/4" I.C.

Rectangle and parallelogram inserts require two digits.

1st digit – No. of 1/8ths in widths

2nd digit – No. of 1/4ths in length

SIZE (I.C.)

0 – Sharp corner (.005R)	4 – 1/16 radius
1 – 1/64 radius	6 – 3/32 radius
2 – 1/32 radius	8 – 1/8 radius
3 – 3/64 radius	12 – 3/16 radius

A – Square insert w/45° chamfer
D – Square insert w/30° chamfer – R
E – Square insert w/15° chamfer – R
²**G** – Square insert w/30° chamfer – L
²**H** – Square insert w/15° chamfer – L
K – Square insert w/15° dbl. chamfer
L – Square insert w/15° dbl. chamfer
N – Truncated triangle insert
P – Flattened corner triangle – R
²**R** – Flattened corner triangle – L

CUTTING POINT CONFIGURATION

T N M G

INSERT TYPE

A – With hole
B – With hole and one countersink
C – With hole and two countersinks
D – Smaller than 1/4" I.C. with hole
E – Smaller than 1/4" I.C. clamp type
F – Clamp type with chip groove on both top surfaces
G – With hole and chip groove on both top surfaces
H – With hole, one countersink and chip groove on one top surface
J – With hole, two countersinks and chip groove on both top surfaces
K – Smaller than 1/4" I.C. with hole, and chip groove on both top surfaces
L – Smaller than 1/4" I.C. clamp type, and chip groove on both top surfaces
M – With hole and chip groove on one top surfaces (except Pos./Neg. insert)
²**N** – Clamp type with chip groove except ceramic–no chip groove
P – With hole and 10° chip groove on both top surfaces (except Pos./Neg. insert)
R – Without hole, with chip groove on one top surface
²**U** – Smaller than 1/4" I.C. clamp type and with chip groove on one top surface
X – Special design

— 4 3 2 — (..)

THICKNESS











Number of 1/32nds on inserts less than 1/4" I.C.
 Number of 1/16ths on inserts 1/4" I.C. and over

CHIPBREAKER
















¹Exact tolerance is determined by the size of the insert.

²Valenite standard only.

Nomenclature- Tool Bar

Bar type	Bar diameter	Bar length	Insert shape	
Steel with coolant-thru A	 <p>Round shanks: shown in 1/16" increments</p> <p>04 =0.250" 05 =0.3125" 06 =0.375" 08 =0.500" 10 =0.625" 12 =0.750" 16 =1.000" 20 =1.250" 24 =1.500" 32 =2.000" 40 =2.500"</p>	 <p>H =4" J =4-1/2" K =5" M =6" R =8" S =10" T =12" U =14" V =16" Y =20"</p>	 C	 D
Carbide C			 K	 R
Carbide with coolant-thru E			 S	 T
Steel S			 V	 W

S 16 T - S C L C R 3

Insert mounting method	Bar style	Insert clearance angle	Hand of tool	Insert I.C size
 C - Clamp lock	 K	 B	 L - Left hand	 <p>Number of 1/8" of inscribed circle</p> <p>2 =0.250" 3 =0.375" 4 =0.500" 5 =0.625" 6 =0.750" 7 =0.875" 8 =1.000"</p>
 M - Multi lock	 F	 C	R - Right hand	
 P - Lever lock	 U	 N		
 S - Screw lock	 L	 P		
	 Q			

SELECTION


1. What would be your primary material for machining? **Stainless Steel, carbon steel, cast iron , titanium** etc. Choose the appropriate grade from manufacturer's **catalog for your application material**.

2. Choose the manufacturer. For ex **Sandvik, Walter and ISCAR** have excellent life but are expensive. Kyocera and TAEGUTEC-Korea offer best value for money.

3. For general turning, go for **WNMG 060408 inserts for roughing. For profiling and finishing, VNMG12T304 inserts** .

4. You would also require tools for boring, drilling, grooving, parting, face grooving, etc.

Mind map



Discussion



10 mins