

# Computer Aided Manufacturing



**Dr.S.RAMABALAN,  
PRINCIPAL,  
E.G.S. PILLAY ENGINEERING COLLEGE,  
NAGAPATTINAM.**



# Cleansing through Breathing

**Nadi Suddhi**  
(Alternate  
Nostril breathing)



1 min

# Recap and review of previous class

Let's  
Recap



5 mins

# Computer Aided Manufacturing

## Unit 4


### **CNC Programming For Machining Centre operations**

Coordinate system - G & M Codes for machining centre - Programming for FANUC and SIEMENS controller -Machining cycles - Linear and circular interpolation, Contouring, rectangular and circular pocketing, drilling, peck drilling, high speed drilling, Back boring, counter boring and tapping cycle - Cutter diameter compensation -Nomenclature of multi-point cutting tool and tool holder -Tool and work holding devices - Automatic Pallet changer.


# CNC Programming – milling




# Sequence of operation – Milling



Shoulder milling




Grooving




Ramping


Wide application only by one tool



Pocket milling



Drilling




Helical milling


## Roughing vs. Finishing



Desired Shape





Rough with Flat  
End-Tool




Finish with Ball  
End-Tool

## Milling Direction


Climb milling has many advantages including better surface finish, longer tool life, and the cutter deflects away from the work rather than into it.



## Up Milling & Down Milling



**Up Milling**




**Down Milling**




## Comparison between Up Milling and Down Milling

SL. NO.	UP MILLING (CONVENTIONAL MILLING)	DOWN MILLING (CLIMB MILLING)
01	Work piece fed in the opposite direction that of the cutter.	Work piece fed in the same direction that of the cutter.
02	Chips are progressively thicker.	Chips are progressively thinner.
03	Strong clamping is required since the cutting force is directed upwards & tends to lift the work piece.	Strong clamping is not required since the cutting force is directed downwards & keep the work piece pressed to the table.
04	Gives poor surface finish, since chips gets accumulated at the cutting zone.	Gives good surface finish, since the chips are thrown away during cutting.
05	Used for hard materials.	Used for soft materials and finishing operations.

# Designation of machine axis



# Programming for Milling



Program as if the tool cutter moves, not the part


## POSITIONING (G00)

The G00 command moves a tool to the position in the workpiece system specified with an absolute or an incremental programming at a rapid traverse rate.

## LINEAR INTERPOLATION (G01)

**G01 IP\_ F\_ ;**

(G91) G01X200.0Y100.0F200.0;




G00	01	Positioning (rapid traverse)	
G01		Linear interpolation (cutting feed)	
G02		Circular interpolation CW or helical interpolation CW	
G03		Circular interpolation CCW or helical interpolation CCW	
G04	00	Dwell, Exact stop	
G10		Programmable data input	
G11		Programmable data input mode cancel	
G15	17	Polar coordinates command cancel	
G16		Polar coordinates command	
G17	02	XpYp plane selection	Xp: X axis or its parallel axis Yp: Y axis or its parallel axis Zp: Z axis or its parallel axis
G18		ZpXp plane selection	
G19		YpZp plane selection	
G20	06	Input in inch	
G21		Input in mm	
G28	00	Automatic return to reference position	
G29		Movement from reference position	
G30		2nd, 3rd and 4th reference position return	
G31		Skip function	
G33	01	Threading	
G40	07	Cutter compensation : cancel	
G41		Cutter compensation : left	
G42		Cutter compensation : right	
G43	08	Tool length compensation +	
G44		Tool length compensation -	
G49	08	Tool length compensation cancel	
G52	00	Local coordinate system setting	
G53		Machine coordinate system setting	


G54	14	Workpiece coordinate system 1 selection
G55		Workpiece coordinate system 2 selection
G56		Workpiece coordinate system 3 selection
G57		Workpiece coordinate system 4 selection
G58		Workpiece coordinate system 5 selection
G59		Workpiece coordinate system 6 selection
G73	09	Peck drilling cycle
G74		Left-handed tapping cycle
G75	01	Plunge grinding cycle (for grinding machine)
G76	09	Fine boring cycle
G77	01	Plunge direct sizing/grinding cycle (for grinding machine)
G78		Continuous-feed surface grinding cycle (for grinding machine)
G79		Intermittent-feed surface grinding cycle (for grinding machine)
G80	09	Canned cycle cancel
		Electronic gear box : synchronization cancellation
G81	09	Drilling cycle or spot boring cycle
		Electronic gear box : synchronization start
G82		Drilling cycle or counter boring cycle
G83		Peck drilling cycle
G84		Tapping cycle
G84.2		Rigid tapping cycle (FS10/11 format)
G84.3		Left-handed rigid tapping cycle (FS10/11 format)
G85		Boring cycle
G86		Boring cycle
G87		Back boring cycle
G88		Boring cycle
G89	Boring cycle	
G90	03	Absolute programming
G91		Incremental programming
G94	05	Feed per minute
G95		Feed per revolution
G98	10	Canned cycle : return to initial level
G99		Canned cycle : return to R point level

## Absolute and incremental programming

G90 X40.0 Y70.0 ;    **Absolute command**  
G91 X-60.0 Y40.0 ;    **Incremental command**




# Milling Direction






## Milling Angles



**Centerline paths are parallel to surfaces**  
**Intersections must be calculated**

## Milling Angles



**Multiple ways to find answer**  
**Exploit this to check your answers**  
**If  $\Delta x \neq \Delta y$ , taper isn't 45°**

# Programming for Milling

## Coordinate Words

**X\_\_\_ Y\_\_\_ Z\_\_\_** ; end point coordinates

**I\_\_\_ J\_\_\_ K\_\_\_** ; arc center coordinates

**U\_\_\_ V\_\_\_ W\_\_\_** ; incremental coordinates in  
absolute programming mode

# Programming for Milling

## Circular Interpolation

**G02/G03 X\_\_ Y\_\_ I\_\_ J\_\_ F\_\_ ;**

**(X,Y) – end point coordinate, (I, J) – arc center coordinate, F – feedrate**


**G02 – CW in positive Z direction**

**G03 – CCW in positive Z direction**

```


G90 G21 M03 S1200
G00 X0 Y0
G01 Z-5
      X30
G03 X54 R12
G01 X82
G02 X108 R13
G01 X123
      X80 Y45
      X40
      Y75
G03 X35 Y80 R5
G01 X20
G03 X0 Y80 R10
G01 Y0
G01 Z10
M05
M30

```



CNCEZ MILLING - I

## SPECIMEN DRAWING



A (5,0) B(0,5) I(10,25)

C(0,45) D(5,50) J(40,25)

E(45,50) F(50,45) K(25,40)

G(50,5) H(45,0) L(25,10)

Program:

:%

: 1005

N05 G90 G21

N10 M06 T01

N15 M03 S1500

N20 G00 X5 Y0 Z5

N25 G01 Z-5 F10

N30 G01 X45

N35 G02 X50 Y5 R5

N40 G01 X50 Y45

N45 G03 X45 Y50 R5

N50 G01 X5 Y50

N55 G02 X0 Y45 R5

N60 G01 X0 Y5

N65 G02 X5 Y0 R5

N70 G01 Z10

N75 G00 X10 Y25

N80 G01 Z-5

N85 G02 X25 Y40 R15

N90 G02 X40 Y25 R15

N95 G02 X25 Y10 R15

N100 G02 X10 Y25 R15


N105 G01 Z10

N110 G00 X0 Y0 Z0

N115 M05

N120 M30

CNCEZ MILLING - II  
SPENIMEN DRAWING



A(0,0)  
 B(5,0)  
 C(45,0)  
 D(50,5)  
 E(50,45)  
 F(45,50)  
 G(5,50)  
 H(0,45)  
 I(0,5)  
 J(25,25)  
 K(25,10)  
 L(40,25)  
 M(25,40)  
 N(10,25)

All Dimenslons Are  
 In mm

Program:

```

:%
: 1006
N05 G90 G21
N10 M06 T01
N15 M03 S1500
N20 G00 X5 Y0
N25 G01 Z-0.5 F10
N30 G01 X45
N35 G03 X50 Y5 R5
N40 G01 X50 Y45
N45 G03 X45 Y50 R5
N50 G01 X5 Y50
N55 G03 X0 Y45 R5
N60 G01 X0 Y5
N65 G03 X5 Y0 R5
N70 G01 Z10
N75 G00 X10 Y25
N80 G01 Z-0.5
N85 G03 X25 Y25 R10.61
N90 G03 X25 Y40 R10.61
N95 G03 X25 Y25 R10.61
N100 G03 X40 Y25 R10.61
N105 G03 X25 Y25 R10.61
N110 G03 X25 Y10 R10.61
N115G03 X25 Y25 R10.61
N120 G03 X10 Y25 R10.61
N125 G01 Z10
N130 G00 X0 Y0
N135 M05 M30
  
```

## Automatic reference position return (G28)

(Example)

```
N1 G28 X40.0 ;
```

(The tool moves to the reference position along the X-axis and the intermediate position (X40.0) is stored.)


```
N2 G28 Y60.0 ;
```

(The tool moves to the reference position along the Y-axis and the intermediate position (Y60.0) is stored.)


```
N3 G29 X10.0 Y20.0 ;
```



# Cutter radius compensation




## G41 - Cutter radius compensation left



G41 D07;

Here, D specifies the address of offset at which the radius of tool will be mentioned

# G42 - Cutter radius compensation right




G42 D07;


Here, D specifies the address of offset at which the radius of tool will be mentioned

## CAM - General Capabilities

**cutter offset = 1/2 cutter diameter**




Move **past** surface  
on outside corner.




Move **to** surface  
on inside corner.

# Part Machining Example



# Part Machining Example



## NC Program Example

```
N001 G90  
N002 M03 S1000
```

```
N003 G00 X0.5 Y1.0 Z0.05  
N004 G01 X0.5 Y1.0 Z-0.6 F10
```

```
N005 G01 X5.0 Y1.0 Z-0.6 F10  
N006 G01 X5.0 Y2.75 Z-0.6 F10  
N007 G03 X4.0 Y3.75 I4.0 J2.75 F10  
N008 G01 X0.5 Y3.75 Z-0.6 F10  
N009 G01 X0.5 Y1.0 Z-0.6 F10
```

```
N010 G01 X0.5 Y1.0 Z0.0 F10  
N011 G00 X0.0 Y0.0 Z0.0
```

```
N012 M05  
N013 M30
```


```
;absolute r  
;spindle on, 1000 RPM
```

```
;rapid traverse  
;advance into part (-z)
```

```
;cut in +x direction  
;cut in +y direction  
;ccw circular interp.(90°)  
;cut in -x direction  
;cut in -y direction
```

```
;retract out of part (+z)  
;rapid traverse
```

```
;spindle off  
;end of program
```




## NC Program Decoding (on machine)

previous block  
no change in X,Y  
N003 G00 X0.5 Y1.0 Z0.05


step (block) #4 in process  
linear interpolation  
10 in/min feedrate  
N004 G01 X0.5 Y1.0 Z-0.6 F10

$$\Delta t = 0.65 \text{ in} \frac{\text{min}}{10 \text{ in}}$$

$$\Delta t = 3.9 \text{ sec}$$











Tool size = 0.25 inch,  
 Feed rate = 6 inch per minute,  
 Cutting speed = 300 rpm,  
 Tool start position: 2.0, 2.0  
 Programming in inches

Motion of tool:  
 $p_0 \rightarrow p_1 \rightarrow p_2 \rightarrow p_3 \rightarrow p_4 \rightarrow p_5 \rightarrow p_1 \rightarrow p_0$


# 1. Set up the programming parameters




## 2. Set up the machining conditions



### 3. Move tool from p0 to p1 in straight line



## 4. Cut profile from p1 to p2



Linear interpolation

target coordinates


```
N040 G01 X3.875 Y9.125
```

or


```
N040 G01 Y9.125
```

X-coordinate does not change → no need to program it

## 5. Cut profile from p2 to p3



## 6. Cut along circle from p3 to p4



circular interpolation, CCW motion


target coordinates

```
N060 G03 X7.366 Y9.125 I6.5 J9.0
```

coordinates of center of circle


```
N060 G03 X7.366 Y9.125 I0.866 J-0.125
```

## 7. Cut from p4 to p5






## 8. Cut from p5 to p1




## 9. Return to home position, stop program



## 10. Complete program

```
N010 G70 G90 G94 G97 M04  
N020 G17 G75 F6.0 S300 T1001 M08  
N030 G01 X3.875 Y3.698  
N040 G01 X3.875 Y9.125  
N050 G01 X5.634 Y9.125  
N060 G03 X7.366 Y9.125 I0.866 J-0.125  
N070 G01 X9.302  
N080 G01 X3.875 Y3.698  
N090 G01 X2.0 Y2.0 M30
```





Tool size = 0.25 inch,  
Feed rate = 6 inch per minute,  
Cutting speed = 300 rpm,  
Tool start position: 2.0, 2.0  
Programming in inches

Motion of tool:  
p0 → p1 → p2 → p3 → p4 → p5 → p1 → p0


# CNC Mill Program (G41 Cutter Radius Compensation Left)

```
N10 T2 M3 S447 F80  
N20 G0 X112 Y-2  
N30 Z-5  
N40 G41  
N50 G1 X95 Y8 M8  
N60 X32  
N70 X5 Y15  
N80 Y52  
N90 G2 X15 Y62 I10 J0  
N100 G1 X83  
N110 G3 X95 Y50 I12 J0  
N120 G1 Y-12  
N130 G40  
N140 G0 Z100 M9  
N150 X150 Y150  
N160 M30
```




# Programming Example (Siemens Controller)

Raw Material




Finished Part



# Program Interpretation (Siemens controller)

**G55 X200 Y80**

**Setting the datum to the lower left corner of the work piece**



# Program Interpretation

**G55 X200 Y80**

**Program 1**

**Program Identification Number**

# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N001 Sequence Number

M06 Tool Change (End Mill with

T1 Tool Number

Diameter=12mm



# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

Start rotating the spindle clockwise with 400 rpm

# Program Interpretation

**G55 X200 Y80**

**Program 1**

**N001 M06 T1**

**N002 M03 rpm 400**

**N003 G01 X-8 Y0 Z0 XYFeed 150**

**Go to Safe Position with feed 150mm/min**

# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X0 Y0 Z-0.5 ZFeed 150

Lower the end mill to determine the depth of cut

# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X0 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

Move from the lower left corner of the work piece to the right lower one cutting with feed=75mm/min



# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400


N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X0 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

Move from the lower left corner of the work piece to the right lower one cutting with feed=75mm/min



# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150


N004 G01 X0 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

Cutting the horizontally up to X=30



# Program Interpretation

**G55 X200 Y80**

**Program 1**

**N001 M06 T1**

**N002 M03 rpm 400**

**N003 G01 X0 Y0 Z0 XYFeed 150**

**N004 G01 X0 Y0 Z-0.5 ZFeed 150**


**N005 G01 X70 Y0 Z-0.5 XYFeed 75**

**N006 G01 X70 Y60 Z-0.5 XYFeed 75**

**N007 G01 X30 Y60 Z-0.5 XYFeed 75**

**N008 G01 X0 Y40 Z-0.5 XYFeed 75**

**Cutting to X=0 & Y=40**



# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X0 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75


N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

N009 G01 X0 Y0 Z-0.5 XYFeed 75

**Complete the counter**





# Program Interpretation

**G55 X200 Y80**

**Program 1**

**N001 M06 T1**

**N002 M03 rpm 400**

**N003 G01 X0 Y0 Z0 XYFeed 150**

**N004 G01 X0 Y0 Z-0.5 ZFeed 150**

**N005 G01 X70 Y0 Z-0.5 XYFeed 75**

**N006 G01 X70 Y60 Z-0.5 XYFeed 75**

**N007 G01 X30 Y60 Z-0.5 XYFeed 75**

**N008 G01 X0 Y40 Z-0.5 XYFeed 75**

**N009 G01 X0 Y0 Z-0.5 XYFeed 75**

**N010 G81 R3 E9 N7 Z-0.5**

**Repeat 7 times blocks from N003 to N009 with incremental offset of Z=-0.5**

# Program Interpretation

**G55 X200 Y80**

**Program 1**

**N001 M06 T1**

**N002 M03 rpm 400**

**N003 G01 X0 Y0 Z0 XYFeed 150**

**N004 G01 X0 Y0 Z-0.5 ZFeed 150**

**N005 G01 X70 Y0 Z-0.5 XYFeed 75**

**N006 G01 X70 Y60 Z-0.5 XYFeed 75**

**N007 G01 X30 Y60 Z-0.5 XYFeed 75**

**N008 G01 X0 Y40 Z-0.5 XYFeed 75**

**N009 G01 X0 Y0 Z-0.5 XYFeed 75**

**N010 G81 R3 E9 N7 Z-0.5**

**N011 M05**

**Spindle Off**

# Program Interpretation

G55 X200 Y80

Program 1

N001 M06 T1

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X0 Y0 Z-0.5 ZFeed 150

N005 G01 X70 Y0 Z-0.5 XYFeed 75

N006 G01 X70 Y60 Z-0.5 XYFeed 75

N007 G01 X30 Y60 Z-0.5 XYFeed 75

N008 G01 X0 Y40 Z-0.5 XYFeed 75

N009 G01 X0 Y0 Z-0.5 XYFeed 75

N010 G81 R3 E9 N7 Z-0.5

N011 M05

N012 M02

End Program

# Program Interpretation

**Tool Change**

**Changing the tool**

# Program Interpretation

Tool Change

**G55 X200 Y80**

Setting the datum to the lower left corner of the work piece



# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

Program Identification Number

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

**N001 M06 T2**

**N001 Sequence Number**

**M06 Tool Change (Drill with Diameter=6mm)**

**T2 Tool Number**

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

Start rotating the spindle clockwise with 400 rpm



# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

Go to Safe Position with feed 150mm/min

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

Stop above the center of the first hole

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2


N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

Start Drill the first hole



# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X-8 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

**N006 G01 X20 Y15 Z10 ZFeed 150**

**Retract to a position above the hole**

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

**N007 G01 X50 Y15 Z10 ZFeed 150**

**Stop above the center of the second hole**

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150


N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

Drill the second hole



# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

**N009 G01 X50 Y15 Z10 ZFeed 150**

**Retract to a position above the second hole**

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

**Stop above the center of the third hole**



# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150


N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

Drill the third hole



# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

**N012 G01 X50 Y45 Z10 ZFeed 150**

**Retract to a position above the third hole**

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75

N012 G01 X50 Y45 Z10 ZFeed 150

N013 M05

Spindle off

# Program Interpretation

Tool Change

G55 X200 Y80

Program 2

N001 M06 T2

N002 M03 rpm 400

N003 G01 X0 Y0 Z0 XYFeed 150

N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150

N005 G01 X20 Y15 Z-10 ZFeed 75

N006 G01 X20 Y15 Z10 ZFeed 150

N007 G01 X50 Y15 Z10 ZFeed 150

N008 G01 X50 Y15 Z-10 ZFeed 75

N009 G01 X50 Y15 Z10 ZFeed 150

N010 G01 X50 Y45 Z10 ZFeed 150

N011 G01 X50 Y45 Z-10 ZFeed 75



N012 G01 X50 Y45 Z10 ZFeed 150

N013 M05

N014 M02

End Program

# Programming Example (Siemens controller)



**G55 X200 Y80**

**Program 1**

**N001 M06 T1**

**N002 M03 rpm 400**

**N003 G01 X0 Y0 Z0 XYFeed 150**

**N004 G01 X0 Y0 Z-0.5 ZFeed 150**

**N005 G01 X70 Y0 Z-0.5 XYFeed 75**

**N006 G01 X70 Y60 Z-0.5 XYFeed 75**

**N007 G01 X30 Y60 Z-0.5 XYFeed 75**

**N008 G01 X0 Y40 Z-0.5 XYFeed 75**


**N009 G01 X0 Y0 Z-0.5 XYFeed 75**

**N010 G81 R3 E9 N7 Z-0.5**

**N011 M05**

**N012 M02**

# Programming Example



**Tool Change**

**G55 X200 Y80**

**Program 2**

**N001 M06 T2**

**N002 M03 rpm 400**

**N003 G01 X0 Y0 Z0 XYFeed 150**

**N004 G01 X20 Y15 Z10 XYFeed 150 ZFeed 150**

**N005 G01 X20 Y15 Z-10 ZFeed 75**

**N006 G01 X20 Y15 Z10 ZFeed 150**

**N007 G01 X50 Y15 Z10 ZFeed 150**

**N008 G01 X50 Y15 Z-10 ZFeed 75**

**N009 G01 X50 Y15 Z10 ZFeed 150**

**N010 G01 X50 Y45 Z10 ZFeed 150**



**N011 G01 X50 Y45 Z-10 ZFeed 75**

**N012 G01 X50 Y45 Z10 ZFeed 150**


**N013 M05**

**N014 M02**

# Exercises




# Programming Examples





- **NC Part Program**
- O1986;
- N10 G21 G94;
- N20 G91 G28 Z0.0;
- N30 T01 M06;
- N40 G90 **G55** G00 X-25.0 Y20; G55- Setting Machine reference datum
- N50 G43 H01 Z50; G43- Cutter length compensation+
- N60 S1000 M03;
- N70 G01 Z-10 F400;
- N80 G41 D01 X20.0 Y20; G41 – Cutter compensation left
- N90 X180.0;
- N100 Y180.0;
- N110 X20.0;
- N120 Y20.0;
- N130 X-25.0 Y-25;
- N140 G40 G00 Z100.0; G40 – Cutter compensation cancel
- N150 G91 G28 Z0.0;
- N160 G91 G28 X0 Y0;
- N170 M05;
- N180 M30;



## CNC Pocket Milling Program Example – Peck Milling

### Main Program

Milling cutter diameter: 10mm

```
N05 G55  
N10 M6 T2 H3 G43  
N15 M3 S1000 F60  
N20 G0 X9 Y9 Z1  
N25 G1 Z0  
N30 M98 P030035  
N35 G0 Z1 G90  
N40 X42 Y38  
N45 G1 Z-2 F30  
N50 X47 F300  
N55 G3 X47 Y38 I-5 J0  
N60 G0 Z100
```

```
N65 G49
```

```
N70 M30
```

### Explanation

**M98 P030035**


this code mean call Subprogram No. 0035 three times.

G43- Tool length compensation +

G49- Tool length compensation cancel

### Subprogram

```
O0035  
N05 G1 Z-2 G91 F30  
N10 X10 F100  
N15 Y36  
N20 X-10  
N25 Y-36  
N30 M99
```



# Fanuc G73 high speed peck drilling cycle program

we have to know which type of drilling is done more in depth. for deep drilling is considered as  $DEPTH/DIA \Rightarrow 5$   
The benefits of peck drilling reduce cycle time. In G73 peck drilling after each drill, tool retract only 1 mm. This drilling cycle is used mostly drill soft materials like; Aluminium

O4231

```
N10 M06 T06 ;  
N20 G90 G80 G17 G00 G54 X0 Y0 ;  
N30 G43 Z100 H11 ;  
N40 M03 S1500 ;  
N50 M08 ;  
N60 G99 G73 Z-55 R5 Q20 F300 ;  
N70 G98 G80 G00 Z100 ;  
N80 M05 M09 M30 ;
```

## DESCRIPTION OF PROGRAM

N10- Tool change command , select tool no. 6

N20- Absolute co-ordinate command , cancel canned cycle command , selection of XY plane, rapid command, work coordinate for tool positioning at X0 and Y0.

N30- Tool height offset compensation command , where tool is 100 along Z axis , tool height code H11.



N40- Spindle on clockwise , speed is 1500 rpm .

N50- Coolant ON .

N60- Return to R-plane in canned cycle , Peck drilling cycle command , Depth of drill is 55 , R- plane distance is 5 , depth of each cut is 20(incremental), feed rate per minute is 300 .

N70- Tool is return at initial position , cancel canned cycle , rapid command where tool is 100 mm up along z axis.

N80- Spindle off , coolant off , main program end .



## Fanuc G81 drilling cycle program with operation repeats

### why we can do operation repeat ?

Following fig. program ; we used K4 command in N60 . The reason is , we can see in the following fig. there is 4 hole drilling on similar distance on X30 and Y0 . Therefore we do not have to need specify every time XY place . In these program in N60 only we used G91 and K4 command .

**G81 X\_ Y\_ Z\_ R\_ F\_ K\_ ;**


Where , **XY**- Position of hole

**Z**- Depth of operation perform

**R**- R plane position.

**F**- cutting feed rate

**K**- no of times operation repeats.



O5124

```
N10 M06 T06 ;  
N20 G90 G80 G17 G00 G54 X0 Y0 ;  
N30 G43 Z100 H4 ;  
N40 M03 S1500 ;  
N50 M07 ;  
N60 G99 G91 G81 X30 Y0 Z-45 R5 K4 F120 ;  
N70 G98 G90 G80 G00 Z100 ;  
N80 M05 M09 M30 ;
```

### DESCRIPTION OF PROGRAM

N10- Tool change command , select tool no. 6

N20- Absolute co-ordinate command , cancel canned cycle command , selection of XY plane, rapid command, work coordinate for tool positioning at X0 and Y0.

N30- Tool height offset compensation command , where tool is 100 along Z axis , tool height code H4.

N40- Spindle on clockwise , speed is 1500 rpm .


N50- Coolant ON .

N60- Return to R-plane in canned cycle , Incremental command, Drilling cycle command, first position is X30 and Y0 Depth of drilling is 45 , R-plane distance is 5 ,feed rate per minute is 120 .


After that second drilling position is X30 from current position and Y0 because we provide incremental command and no of repetition K4 (repeating operation), similarly reaming operation will perform.

N70-Tool return initial position ,Absolute co-ordinate command(cancel incremental command), cancel canned cycle , rapid command , where tool along Z axis is 100 .

N80- Spindle off , coolant off, Main program end .



## Programming Example



BLANK SIZE

100\*100\*20

DIA. 8, FIVE HOLES

HOLE1 (20,20)


HOLE2 (20,80)

HOLE3 (80,80)

HOLE4 (80,20)

HOLE5 (50,50)


- **NC Part Program**
- O1975;
- N10 G21 G94;
- N20 G91 G28 Z0.0;
- N30 T01 M06;
- N40 G90 G54 G00 X20.0 Y20.0;
- N50 G43 H01;
- N60 S1200 M03 Z0.0;
- **N70 G99 G81 X20.0 Y20.0 Z-23.0 R5.0 F300;**
- N80 Y80.0;
- N90 X80.0;
- N100 Y20.0;
- N110 X50.0 Y50.0;
- N120 G80 G00 Z100.0 M05;
- N130 G91 G28 Z0;
- N140 G28 X0 Y0;
- N150 M30;



BLANK SIZE  
 100\*100\*20  
 DIA. 8, FIVE HOLES  
 HOLE1 (20,20)  
 HOLE2 (20,80)  
 HOLE3 (80,80)  
 HOLE4 (80,20)  
 HOLE5 (50,50)



- O1975;
- N10 G21 G94;
- N20 G91 G28 Z0.0;
- N30 T01 M06;
- N40 G90 G54 G00 X10.0 Y10.0;
- N50 G43 H01;
- N60 S1200 M03 Z50;
- N70 G99 G81 X10.0 Y10.0 Z-5 R5.0 F300;
- N80 G91 X10 Y10 K8;
- N90 G00 Z50 M05;
- N100 G91 G28 Z0.0;
- N110 G91 G28 X0.0 Y0.0;
- N120 T02 M06;
- N130 G90 G54 G00 X40.0 Y10.0;
- N140 G43 H02;
- N150 S1200 M03 Z50;
- N160 G00 Z5 ;

- N170 G01 Z-3 F60;
- N180 X90 ;
- N190 Y20;
- N200 X40;
- N210 Y10;
- N220 G00 Z50;
- N230 G00 X10 Y80 ;
- N240 G00 Z5;
- N250 G01 Z-3 F60;
- N260 X60;
- N270 Y90;
- N280 X10;
- N290 Y80;
- N300 G00 Z50 M05;
- N310 G91 G28 Z0;
- N320 G28 X0 Y0:
- N330 M30;





# Exercises



## Fanuc G82 counter boring cycle / Drilling cycle

G82 cycle is used for normal drilling . Cutting feed is performed to the bottom of the hole .At the bottom , a dwell is performed , the tool is retracted. This cycle is used to drill hole more accurately with respect to depth.

**G82 X\_ Y\_ Z\_ R\_ P\_ F\_ K\_;**

Where , **XY**- Position of hole

**Z**- Depth of operation perform


**R**- R plane position

**P**- Dwell time when tool reach at bottom

**F**- cutting feed rate

**K**- no of times operation repeats.

**Operation :-** First tool positioning at XY axis , after the tool rapidly traverse up to R-plane level , after that tool is start drilling operation . When the bottom of the tool has been reached, a dwell is performed. Then tool is retracted rapidly.



O5124

```
N10 M06 T04 ;  
N20 G90 G80 G17 G00 G54 X0 Y0 ;  
N30 G43 Z100 H4 ;  
N40 M03 S1500 ;  
N50 M07 ;  
N60 G99 G82 X20 Y20 Z-10 R5 P1000 F120 ;  
N70 X50 Y20 ;  
N80 G98 G80 G00 Z100 ;  
N90 M05 M09 M30 ;
```

#### DESCRIPTION OF PROGRAM

N10- Tool change command , select tool no. 4

N20- Absolute co-ordinate command , cancel canned cycle command , selection of XY plane, rapid command, work coordinate for tool positioning at X0 and Y0.

N30- Tool height offset compensation command , where tool is 100 along Z axis , tool height code H4.

N40- Spindle on clockwise , speed is 1500 rpm .


N50- Coolant ON .

N60- Return to R-plane in canned cycle , counter drilling command ,first drilling position is X20 and Y20 Depth of drilling is 10 , R- plane distance is 5 ,dwell time is 1 sec , feed rate is 120.

N70- Second drill position where X 50 and Y20 and drilling depth is 10.

N80-Tool return initial position , cancel canned cycle , rapid command , where tool along Z axis is 100 .

N90-Spindle off , coolant off, Main program end .



## Fanuc G83 peck drilling cycle program

G83 peck drilling cycle perform intermittent cutting feed to the bottom of the hole while removing shaving from the hole.

**G83 X\_ Y\_ Z\_ R\_ Q\_ P\_ F\_ K\_**

Where , **XY**- Position of hole


**Z**- Depth of operation perform

**R**- R plane position.

**Q**- depth of each cut

**F**- cutting feed rate

**K**- no of times operation repeats.



**Operation:-** In above fig Q represent depth of each cut . Cutting depth is always incremental value (suppose first cut is 20 mm then tool take second cut is increment by 20mm it means total depth is 40 mm ). After each cut tool return at R plane , when operation is end tool return at initial position .

O5124

```
N10 M06 T05 ;  
N20 G90 G80 G17 G00 G54 X0 Y0 ;  
N30 G43 Z100 H4 ;  
N40 M03 S1000 ;  
N50 M07 ;  
N60 G99 G83 X10 Y10 Z-40 R5 Q10 F75  
N70 X60 Y10 ;  
N80 X10 Y60 ;  
N90 X60 Y60 ;  
N100 G98 G80 G00 Z100 ;  
N110 M05 M09 M30 ;
```

### DESCRIPTION OF PROGRAM

N10- Tool change command , select tool no. 5

N20- Absolute co-ordinate command , cancel canned cycle command , selection of XY plane, rapid command, work coordinate for tool positioning at X0 and Y0.

N30- Tool height offset compensation command , where tool is 100 along Z axis , tool height code H4.

N40- Spindle on clockwise , speed is 1000 rpm .

N50- Coolant ON .

N60- Return to R-plane in canned cycle , Peck drill command ,first drilling position is X10 and Y10 Depth of boring is 40(from R-plane) , R- plane distance is 5 , each cut is 10 mm , feed rate per minute is 75 .


N70- Second drilling position is X60 and Y10;

N80- Third drilling position is X10 and Y60;

N90- Fourth drilling position is X60 and Y60;

N100- Tool return initial position , cancel canned cycle , rapid command , where tool along Z axis is 100 .

N110- Spindle off , coolant off, Main program end .



## G84 Tapping Cycle Example CNC Program

Fanuc G84 cycle performs tapping. In this tapping cycle, when the bottom of the hole has been reached, the spindle is rotated in the reverse direction.

**G84 X\_ Y\_ Z\_ R\_ P\_ F\_ K\_**

Where , **XY**- Position of hole


**Z**- Depth of operation perform from retraction plane

**R**- R plane position.(retraction plane)

**P**- Dwell time

**F**- cutting feed rate

**K**- no of times operation repeats.



**Operation:-** Tapping is performed by rotating the spindle clockwise. When the bottom of the hole has been reached, the spindle is rotated in the reverse direction for retraction. This operation creates threads.

O5124

N10 M06 T07 ;

N20 G90 G80 G17 G00 G54 X0 Y0 ;

N30 G43 Z100 H1 ;

N40 M03 S1000 ;

N50 M07 ;

N60 G99 G84 X10 Y10 Z-30 R5 P300 F1.25 ; [A]


N70 X80 Y10 ; [B]

N80 X10 Y70 ; [C]

N90 X80 Y70 ; [D]

N100 G98 G80 G00 Z100 ;

N110 M05 M09 M30 ;



### DESCRIPTION OF PROGRAM

N10- Tool change command , select tool no. 7

N20- Absolute co-ordinate command , cancel canned cycle command , selection of XY plane, rapid command, work coordinate for tool positioning at X0 and Y0.

N30- Tool height offset compensation command , where tool is 100 along Z axis , tool height code H1.

N40- Spindle on clockwise , speed is 1000 rpm .

N50- Coolant ON .

N60- Return to R-plane in canned cycle , tapping cycle command ,first tapping position is X10 and Y10 Depth of tapping is 30(from R-plane) , R-plane distance is 5 , dwell time 300 , feed rate is 1.25 .[A]

N70- Second tapping position is X80 and Y10; [B]

N80- Third tapping position is X10 and Y70; [C]

N90- Fourth tapping position is X80 and Y70; [D]

N100- Tool return initial position , cancel canned cycle , rapid command , where tool along Z axis is 100 .

N110- Spindle off , coolant off, Main program end .

## Fanuc G85/G86 boring cycle

Fanuc G85/G86 cycle is used to bore a hole .

**G85/G86 X\_ Y\_ Z\_ R\_ F\_ K\_**


Where , **XY**- Position of hole

**Z**- Depth of operation perform from retraction plane

**R**- R plane position.(retraction plane)

**F**- cutting feed rate

**K**- no of times operation repeats.



**Operation:-** First positioning of tool at XY plane. After that tool rapidly traverse up to R plane , then boring operation start from R plane to point Z. After that tool rapidly return to initial position.



O5130

N10 M06 T08 ;

N20 G90 G80 G17 G00 G54 X0 Y0 ;

N30 G43 Z100 H1 ;

N40 M03 S1000 ;

N50 M07 ;

N60 G99 G86 X10 Y25 Z-30 R5 F100 ;

N70 X40 Y10 ;

N80 G98 G80 G00 Z100 ;

N90 M05 M09 M30 ;

### DESCRIPTION OF PROGRAM

N10- Tool change command , select tool no. 8

N20- Absolute co-ordinate command , cancel canned cycle command , selection of XY plane, rapid command, work coordinate for tool positioning at X0 and Y0.

N30- Tool height offset compensation command , where tool is 100 along Z axis , tool height code H1.

N40- Spindle on clockwise , speed is 1000 rpm .


N50- Coolant ON .

N60- Return to R-plane in canned cycle , Boring cycle command ,first boring position is X10 and Y25 Depth of tapping is 30(from R-plane) , R- plane distance is 5 , feed rate is 100 .

N70- Second boring position is X40 and Y10; [

N80- Tool return initial position , cancel canned cycle , rapid command , where tool along Z axis is 100 .

N90- Spindle off , coolant off, Main program end .



## G87 Back Boring cycle

The G87 Back Boring cycle is a special cycle, its practical usage is limited due to the special tooling and setup requirements. Use the G87 Cycle only if the total costs can be justified economically. The boring bar must be set very carefully, it must be preset to match the diameter required for backboring, its cutting point must be set in the spindle oriented mode, facing the opposite direction than the shift direction.

### Code line for G87 Back Boring cycle:

There are two program formats available for the G87 back boring canned cycle. Unfortunately G99 is never used with the G87 cycle.


First one using the Q, which is commonly used:

```
N100 G98 G87 X... Y... R... Z... Q... F...
```

Second one using I and J:


```
N100 G98 G87 X... Y... R... Z... I... J... F...
```

### Diagram for G87 Back Boring cycle:



## Steps for the G87 Back Boring cycle:

1. Rapid motion to XY position of the hole position.
2. Spindle Rotation Stop.
3. Spindle Orientation.
4. Shift OUT (OSS) by the Q value or shift by the amount and direction of I and J.
5. Rapid motion to the R level, i.e., to the bottom of the hole position.
6. Shift IN (OSS) by the Q value or shift back in the opposite direction of I and J.
7. Spindle rotation ON (M03).
8. Feedrate motion to the depth in Z.
9. Spindle rotation STOP.
10. Spindle orientation.
11. Shift OUT (OSS) by the Q value or shift by the amount and direction of I and J.
12. Rapid motion to the Initial level, i.e., to the top of the hole position.
13. Shift (OSS) IN by the Q value or shift back in the opposite direction of I and J.
14. Spindle rotation ON.



# Milling Tools

## HSS Flat Endmills

4-flute



3-flute



2-flute



## Carbide Insert Endmills



# Milling Tools (Cont'd)

## HSS Ball Endmills

4-flute



3-flute



2-flute double ended




## Carbide Insert Ball Endmills






# Milling cutter nomenclature

## NOMENCLATURE OF MILLING CUTTER






**FIGURE 42—Shown here is the code key for milling-machine insert designations. (Courtesy of Carbide Inc., www.carbide.com)**




# Tool holder Selection – Milling






**FIGURE 38**—The spindles of milling machines have standard dimensions to ensure compatibility with different manufacturers' products. These tapers are a self-releasing type so that tools can be rapidly changed by automatic toolholder changes.



N- GAGE DIAMETER OF TAPER  
 O- TAP DRILL SIZE FOR DRAW-IN-THREAD  
 P- DIAMETER OF NECK  
 M- SIZE OF THREAD FOR DRAW-IN-BOLT UNC-2B  
 R- PILOT DIAMETER  
 S- LENGTH OF PILOT  
 T- MINIMUM LENGTH OF USABLE THREAD  
 U- MINIMUM DEPTH OF CLEARANCE HOLE


V- DISTANCE FROM REAR OF FLANGE TO END  
 OF ARBOR  
 W- CLEARANCE OF FLANGE FROM GAGE DIAMETER  
 X- TOOL SHANK CENTERLINE TO DRIVING SLOT  
 Y- WIDTH OF DRIVING SLOT  
 Z- DISTANCE FROM GAGE LINE TO BOTTOM  
 OF C-BORE  
 K- DEPTH OF 60° CENTER  
 L- DIAMETER OF C-BORE

**FIGURE 39—***Toolholders have standard dimensions to ensure proper fit within spindles of machine tools. (Copyright © ANSI 1997-2000, ANSI B5.18-1972, R1991. Source: Machinery's Handbook, 25th Edition, page 920, Table 2, Essential Dimensions of American National Standard Tool Shanks for Milling Machines)*




**FIGURE 48—Hydraulic toolholders provide high clamping forces, good concentricity, and few unbalances. Clamping forces are generated by a piston acting on a hydraulic reservoir within the end of the toolholder that forces an expanding sleeve to grip the cutting tool.**




***FIGURE 49—High centrifugal forces in the rotating spindle actually cause the inside diameter of the spindle to increase slightly. This change can cause the toolholder to be drawn farther into the spindle, causing a change in the Z-axis position and also making removal of the tool difficult when the spindle is stopped.***



**FIGURE 50—The HSK system, which uses a hollow shank and taper, is a type of spindle system for machine tools.**



# Work Holding Device - Milling



# Equipment

## Pallets

The workpiece is placed on a pallet (module) which can be oriented in different directions by the machine

## Automatic Pallet Changers

When the workpiece is finished, automatic pallet changers remove it and replace it with another workpiece



# Pallets



Example of a part mounted on a pallet

Courtesy Toth Industries

# Pallet Changers




FIGURE 24.4 (a) Schematic illustration of the top view of a horizontal-spindle machining center showing the pallet pool, set-up station for a pallet, pallet carrier, and an active pallet in operation (shown directly below the spindle of the machine). (b) Schematic illustration of two machining centers with a common pallet pool. Various other arrangements are possible in such systems. *Source:* Hitachi Seiki Co., Ltd.

# Discussion



10 mins